Pathway to Certification: Level 2 Inspector

1 CHECK REQUIREMENTS

Ensure you meet the *minimum requirements* to upgrade to a Level 2 Visual Welding Inspector.

2 TRAINING

CWB Course

Enrollment in **CWB Level 2 Inspector course** (in-class or asynchronous).

Completion of all courses and minimum 70% score on all chapter and final course exams.

CWB Micro-credentials

Enrollment in **CWB Level 2 Inspector micro-credentials** (11 micro-credentials).

Completion of all 11 micro-credential courses and minimum 70% score on all chapter exams.

Prior experience

Completion of closed book exam and practical examination.

3 APPLICATION

Submit grades and completion certificate along with *Application* & *Vision* forms to CWB Personnel Certification Team to be eligible to write a short version of the closed book exam.

Submit grades and completion certificate of all micro credentials along with *Application* & *Vision* forms to CWB Personnel Certification Team to be eligible to write a short version of the closed book exam.

4 EXAMINATION

Completion of closed book exam and practical examination.

Note: Exams can be remotely proctored or in-person for closed book and practical.

5 CERTIFICATION

Level 2 Inspector Certification is granted.